



NOTES	
1	Socket for wooden beam that supported the fractured section of the overhang. The beam and the section have fallen away.

