


NOTES	
1	Entry filled with debris; original stairs or ramp not visible.
2	Top portion of pillars destroyed.
3	Jambes at either end are badly damaged.
4	Jambes at either end are badly damaged but may be parts of two doors piercing the wall between chambers C and Cb.
5	Bottom portion of walls and gates destroyed.

Due to the severely damaged condition of the tomb, the location and existence of walls, doorways, and pillars are largely speculative.



N 97,922.609
E 93,917.098
Elev 113.880

