


QV 11
 N 97,970.875
 E 93,998.448
 Elev 109.603
 Axis 173° 23' 44"

QV 12
 N 97,966.454
 E 93,993.768
 Elev 110.995
 Axis 173° 23' 44"



NOTES	
1	Top of pit.
2	Dimensions of wall approximate.
3	Size, location of opening approximate.
4	Possibly the original line of back wall.
5	Ceiling collapsed at rear of chamber.
6	Rough stone retaining wall.
7	Dimensions of shaft approximate.
8	Dimensions of doorway approximate.
9	Dimensions of ceiling approximate.

Survey notes incomplete, section of QV 12 could not be resolved.

Courtesy of the Getty Conservation Institute and the Ministry of Tourism and Antiquities.