



NOTES	
1	Top of pit.
2	Lintel broken; measurements uncertain.
3	Series of six hand-holds cuts into side of pit shaft; dimensions and locations approximate.
4	Doorway badly damaged; no signs of jambs remain.
5	Ceiling collapsed in center of chamber C.
6	Doorway badly damaged; original jambs estimated.
7	Entire section of wall collapsed; signs of original wall remain at ceiling.

Courtesy of the Getty Conservation Institute and the Ministry of Tourism and Antiquities.