



NOTES

- | | |
|---|--|
| 1 | Modern steps; no evidence of original steps. |
| 2 | Modern retaining wall. |
| 3 | Both door jambs reconstructed. |
| 4 | Door jamb reconstructed. |
| 5 | Pillar damaged and partially reconstructed. |
| 6 | Lintel and both door jambs reconstructed. |

